

APPLICATION INSTRUCTIONS

Graffiti

Printable flex film with the best compromise between cuttability and touch.
Soft, elastic, easy to cut and with a very good wash-fastness.

OEKO
TEX®

STANDARD
100

CQ 730/3
IFTH

www.oeko-tex.com

Certified for
HP Latex Inks

FEATURES:



PU
water-
based



60µ



Cotton, polyester,
blended fabrics.
Also suitable for most water
repellent coated textiles.



EcoSolvent (incl. TrueVis),
Solvent, Latex

CUTTING CONDITIONS:



Blade
30 - 45°



low/
medium



30 - 40 cm/s



1. Print and cut



2. Weed design



3. Apply tape

TRANSFER CONDITIONS COTTON:



150°C



10 s



medium/
high



Hot peel



60°C

TRANSFER CONDITIONS POLYESTER:



125°C



10 s



medium/
high



Hot peel



60°C



4. Transfer, remove tape,
done !



Printing profiles at www.seftextile.com

Recommended transfer tape: FlexTape

Drying time: Depending on ink and conditions 1 - 6h

For small designs, it can be useful to first apply the tape over the whole surface and then to weed it from the back.

► PACKAGING

	
50 cm	25 m
75 cm	25 m

Store in a cool and dry place; protect against the influence of light when stored. We recommend not to exceed a storage period of 12 months. The technical specifications rest on extensive tests and technical research. Due to the variety of possible influences during refinement, and use, the specifications should be viewed as reference values. We recommend a suitability test on the original material. A legally binding warranty of specific characteristics cannot be derived from our specifications.